



Centurion Mines Corporation — Mammoth Mine Permit Photos




Mammoth Mine Surface Plant, looking southwest across mine complex, October 1994



Mammoth Mine Surface Plant looking west; 1) foreground: shop - dry complex; 2) left foreground: compressor building; 3) left center: mine office; 4) center: car dumper, October 1994



Mammoth Mine Surface Plant, October 1994
Looking north on access road; right side of photo: car dumping stand
center of photo: old timber framing shed



Mammoth Mine Surface Plant looking west, October 1994

Centurion Mines Corporation — Mammoth Mine Permit Photos




Mammoth Mine Surface Plant looking west, October 1994

- 1) Far building: old mule barn; 2) near building - timber framing shed;
- 3) Note: area of cement boxes will be storage area for the mine, i.e. timber, etc.



Mammoth Mine Surface Plant, October 1994
Looking north across area of proposed mine run surge pile



Mammoth Mine Surface Plant, October 1994
Looking west across proposed surge pile stacking area



Mammoth Mine Surface Plant, October 1994
Looking southeast across proposed ore stockpiling area and proposed area where
crusher will be located



Mammoth Mine Surface Plant, October 1994
Picture showing vegetation in area proposed for ore stacking